


IRAQ - Hasansham M2 Camp

Tent Condition - Updated 26 January 2017

Density of Sample Tents Experiencing Flooding



Sample Tent Location



- Tents with Secondary Cover
- Tents without Secondary Cover

Camp Infrastructure

- Fence
- Sector
- Block
- Under Construction
- Office / Facility
- Entrance
- Health
- NGO Office
- Shop
- Bakery
- Road
- River

Layout of Single Block

- Tent
- Shower
- Water Tank
- Latrine
- Kitchen
- Tap Stand



**GPS Coordinates
of Camp Location:**
Longitude: 43°32'51.806" E
(43.547724)
Latitude: 36°20'17.81" N
(36.338281)

Thematic Data: 26/01/2017 - REACH
Administrative boundaries: GADM
Background imagery: ESRI, DigitalGlobe
- WV02 - 24/06/2010
Projection: WGS 1984 UTM Zone 38N
Contact : iraq@reach-initiative.org
File: IRQ_Map_IDP_HasanshamM2_
Tentcondition_17Apr2017

Note: Data, designations and boundaries
contained on this map are not warranted to be
error-free and do not imply acceptance by the
REACH partners, associates or donors
mentioned on this map.



53% do not utilize secondary cover
45% experience flooding
100% do not have concrete base

Note:

Based on 99 Samples taken within the camp, following the same method-
ology as the camp profiling exercise, the assessment used household level
sampling with a 95% confidence level and 10% margin or error.

Scale 1: 2,200
0 20 40 80 120 160 Meters