


IRAQ - Khazer M1 Camp

Tent Condition - Updated 19 January 2017

Density of Sample Tents Experiencing Flooding



Sample Tent Location


- Tents with Secondary Cover
- Tents without Secondary Cover

Camp Infrastructure

- Fence
- Sector (A-Z)
- Unoccupied Area
- Office / Facility
- Entrance
- Gate
- Office
- NGO Office
- Water Tank (3)
- Borehole (3)
- Shop
- Bakery
- Parking
- Generator
- Storage
- Road
- River

Layout of Single Block

- Tent
- Shower
- Water Tank
- Latrine
- Kitchen
- Tap Stand



52% do not utilize secondary cover

62% experience flooding

100% do not have concrete base

Note:

Based on 99 Samples taken within the camp, following the same methodology as the camp profiling exercise, the assessment used household level sampling with a 95% confidence level and 10% margin or error.

GPS Coordinates of Camp Location:

Longitude: 43°32'19.047" E
(43.538624)
Latitude: 36°18'32.324" N
(36.308979)

Thematic Data: 19/01/2017 - REACH
Administrative boundaries: GADM
Background imagery: ESRI, DigitalGlobe
- WV02 - 24/06/2010
Projection: WGS 1984 UTM Zone 38N
Contact: iraq@reach-initiative.org
File: IRQ_Map_IDP_KhazerM1_
_Tentcondition_17Apr2017

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the REACH partners, associates or donors mentioned on this map.

