


# IRAQ - Kirkuk Governorate - Laylan 1 Camp



## Tent Condition - Updated 23 January 2017

For Humanitarian Purposes Only  
Production date : 24 April 2017








### Density of Sample Tents Experiencing Flooding



### Sample Tent Location

-  Tents with Secondary Cover
-  Tents without Secondary Cover




### Camp Infrastructure

-  Fence
-  Sector (A - Z)
-  Office / Facility
-  Entrance
-  NGO Office
-  Water Tank (106)
-  Borehole (2)

**GPS Coordinates  
of Camp Location:**  
Longitude: 44° 31' 48.575" E  
(44.51667)  
Latitude: 35° 19' 46.44" N  
(35.32957)

Thematic Data: - 23/01/2017 REACH  
Administrative boundaries: GADM  
Background imagery: Airbus - Pleiades  
- 29/07/2016  
Projection: WGS 1984 UTM Zone 38N  
Contact : iraq@reach-initiative.org  
File: IRQ\_MAP\_IDP\_Laylan1\_  
Tentcondition\_24Apr2017

Note: Data, designations and boundaries  
contained on this map are not warranted to be  
error-free and do not imply acceptance by the  
REACH partners, associates or donors  
mentioned on this map.



### Note:

Based on 115 Samples taken within the camp,  
following the same methodology as the camp  
profiling exercise, the assessment used  
household level sampling with a 95%  
confidence level and 10% margin of error.

**7%** do not utilize secondary cover  
**15%** experience flooding  
**6%** do not have concrete base