



buildings total*

39%

buildings within 50m of an unimproved water source** of neighbourhood within 50m of unimproved water sources


UNOSA

*according to OSM extract from 27 March

**unimproved water sources are open wells, open water catchments and other unprotected water sources identified through a rapid infrastructure assessment of Beira by REACH. Other water sources are protected wells, motorized/hand pumped boreholes, tapstands, and municipal piped water. REACH was unable to map the piped water system due to its extent, so water analysis is focused on highlighting areas with unimproved sources.

Data sources: Water Infrastructure - REACH Beira Bairros - INGC Administrative Boundaries (0-3) - OCHA Satellite Imagery: WorldView-2 from 26 March 2019 Copyright: ©DigitalGlobe 2019 Source: US Dept of State Humanitarian Information Unit, NextView License


Legend



-- Bairros

Nhaconjo - Unimproved Water Sources - As of 17 April 2019






Coordinate System:GCS WGS 1984 File: MOZ_Map_CycloneIda_WaterAnalysis_Nhaconjo_25APR2019 Contact: reach.mapping@impact-initiatives.org

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the REACH partners, associated, donors mentioned on this map.

For Humanitarian Purposes Only Production date: 25 April 2019





Funded by **European Union Civil Protection and** Humanitarian Aid

6