


59% do not utilize secondary cover

17% experience flooding

0% do not have concrete base

Note:

Based on 106 Samples taken within the camp, the assessment used household level sampling with a 95% confidence level and 10% margin or error.



Density of Sample Tents Experiencing Flooding

High : 3
(Tents per Hectare)
Low : 1

Sample Tent Location

▲ Tents with Secondary Cover

▲ Tents without Secondary Cover

Camp Infrastructure

- Fence
- Sector (A - M)
- Under Construction
- Office / Facility
- Entrance
- Camp Management
- Office
- Distribution
- Borehole (6)

- Water Tank (12)
- Storage
- Bakery
- Generator
- Grey Water

Data sources:
Camp Infrastructure: 2 January 2017, REACH Initiative
Satellite Imagery: Airbus - Pleiades - 02/09/2016
Coordinate System: WGS 1984 UTM Zone 38N
Projection: Transverse Mercator
File: IRQ_MAP_IDP_Chamisku_Tentcondition_11Apr2017
Contact: iraq@reach-initiative.org

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the REACH partners, associated, donors mentioned on this map.