
# CAMP COORDINATION

#### Blocked Toilets (%) in Housing Blocks and Communal Buildings



••••• Fence


ĥ

Sector (A - M)

Bridge

Entrance

### **IRAQ - Duhok Governorate - Bersive 2** WASH Facilities - Blocked Toilets - May 2016



Thematic Data: 24/04/2016 - REACH Administrative boundaries: GADM Background imagery: Airbus 09/02/2016 Projection: WGS 1984 UTM Zone 38N


Contact : iraq@reach-initiative.org File:IRQ\_Map\_IDP\_Bersive2\_Blocked Toilets\_12June2016

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the REACH partners, associates or donors mentioned on this map.




# CAMP COORDINATION

#### **Overflowing Toilets (%)** in Housing Blocks and Communal Buildings



## **IRAQ - Duhok Governorate - Bersive 2** WASH Facilities - Overflowing Toilets - May 2016



••••• Fence Sector (A - M) Entrance ĥ Bridge Rainwater Channel

Thematic Data: 24/04/2016 - REACH Administrative boundaries: GADM Background imagery: Airbus 09/02/2016 Projection: WGS 1984 UTM Zone 38N


Contact : iraq@reach-initiative.org File:IRQ\_Map\_IDP\_Bersive2\_Overflowing Toilets\_12June2016

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the REACH partners, associates or donors mentioned on this map.




# CAMP COORDINATION

#### Non-functioning Showers (%) in Housing Blocks and Communal Buildings



## **IRAQ - Duhok Governorate - Bersive 2** WASH Facilities - Non-functioning Showers - May 2016



••••• Fence Sector (A - M) Entrance ĥ Bridge Rainwater Channel

Thematic Data: 24/04/2016 - REACH Administrative boundaries: GADM Background imagery: Airbus 09/02/2016 Projection: WGS 1984 UTM Zone 38N

Contact : iraq@reach-initiative.org File:IRQ\_Map\_IDP\_Bersive2\_Non FunctioningShowers\_12June2016

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the REACH partners, associates or donors mentioned on this map.



# CAMP COORDINATION AND CAMP MANAGEMENT

#### Non-functioning Tap Stands (%) in Housing **Blocks and Communal** Buildings



•••••• Fence

ĥ


\_\_\_\_ Sector (A - M)

Bridge

Entrance

Rainwater Channel

## **IRAQ - Duhok Governorate - Bersive 2** WASH Facilities - Non-functioning Tap Stands - May 2016



Thematic Data: 24/04/2016 - REACH Administrative boundaries: GADM Background imagery: Airbus 09/02/2016 Projection: WGS 1984 UTM Zone 38N

Contact : iraq@reach-initiative.org File:IRQ\_Map\_IDP\_Bersive2\_Non FunctioningTaps\_12June2016

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the REACH partners, associates or donors mentioned on this map.

