



Analysis of rounds 1 through 4 of WASH infrastructure data collected on behalf of the WASH Sector and the ISCG indicate that proximity of functioning handpumps/tubewells to latrines continues to be a concern, with nearly 33% of all functioning handpumps/tubewells too close (<10m) to latrines.

This map highlights the key infrastructure in question, both the handpumps/tubewells and latrines, that are too close to each other, as well as shelters whose nearest functioning handpump/tubewell is less than 10m from a latrine.

For more information, please contact: reach.mapping@impact-initiatives.org