
SOUTH SUDAN - Eastern Equatoria State, Torit County

Torit Town water test results - As of 20 September 2019





- Borehole motorized (4)
- Borehole manual (39)
- Tapstand (6)
- Water kiosk(1)
- Storage tank (2)

- Borehole motorized (4)
- Borehole manual (17)
- Tapstand (1)
- Storage tank(4)
 - Unprotected well (1) Water kiosk (3)

Secondary road Torit town extent Other roads

River Kinete

Administrative areas Swampy area

Reported referred area name

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the REACH partners, associates, donors mentioned on this map.

Funded by:



Contact: south.sudan@reach-initiative.org

Deutsche Gesellschaft

REACH Initiatives of IMPACT initiatives of ACTED and UNOSA