




Syria - City of Deir ez-Zor

Shelter Damage Assessment as of 10th May 2015

For Authorized Distribution Only
For Humanitarian Purposes Only
Production Date:22th June 2015




Shelter damage assessment



399 Buildings
Damaged Between
May 2014 and May 2015

87 destroyed
127 severely damaged
185 moderately damaged

Damage Density as of 10th May 2015



Damage Zones

- Destroyed
- Severe Damage
- Moderate Damage,
- Severe Damage, low density
- Moderate Damage, low density

Satellite Data: WorldView-2 - Image Date: 10.05.2015
Resolution: 50 cm - Copyright: Airbus
Shelter Damage Assessment Data: UNOSAT/REACH
Projection: WGS 1984 UTM zone 37N
File:
REACH_SYR_Map_DeirEzZor_ASMT_SDcity_22JUN15_A3
Contact: reach.mapping@impact-initiatives.org



Note: Data, designations and boundaries contained in this map are not warranted to be error-free and do not imply acceptance by the REACH partners, donors and associated persons mentioned in this map.