



● Latrines Block

○ Washrooms

○ Desludging Tank

○ Bio-gas Digester

■ Latrines Block (Non functioning)

■ Washrooms (Non functioning)\*

✚ Open Defecation Area

● Hand Pump - Tubewell

■ Water Tap

■ Water Tank

■ Unimproved well

■ Unimproved Water Source

■ Water Tap (Non functioning)\*

■ Hand Pump - Tubewell (Non functioning)\*

■ Clinic

■ Nutrition Center

■ Child Friendly Space

■ Women Friendly Space

■ Learning Center / Madrassah

■ Shop(s)

■ Distribution Center

■ Mosque

■ Street Light

■ Zone Boundary

■ Shelter Footprints (as of 26th October)

■ River

--- Primary Footpaths

Data Sources:  
Camp Infrastructure - REACH  
Site Boundaries - REACH / OCHA ROAP  
Shelter Footprints - REACH / UNOSAT  
Satellite Imagery: Pleiades from 26 October 2017  
Copyright: CNES  
Source: Airbus DS

Coordinate System: WGS 1984 UTM Zone 46N  
Projection: Transverse Mercator  
File:  
reach\_bgd\_map\_coxsbazar\_hakimpara\_infrastructure\_02122017\_a1

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the REACH partners, associated, donors mentioned on this map.

\*Due to missing information in data collected by enumerators, the number of non-functioning facilities may be higher than indicated.

REACH

An initiative of  
IMPACT Initiatives  
ACTED and UNOSAT