

WASH Site Profile - All

Ukhia / Teknaf, Cox's Bazar, Bangladesh (July 2018)



Summary

This profile provides an overview of water, sanitation and hygiene (WASH) infrastructure within All in Ùkhia / Teknaf, Cox's Bazar. Primary data for this round was collected from 29th May to 22nd 2018.¹ Findings should July be indicative only. Full considered camp dataset is available on HDX.

Site Overview

of individuals: 883,727

of households: 203,488

of shelters: 175,820

of individuals

5 per shelter:

Key WASH Infrastructure

of latrines: 42,923 (% functional and

(77%)

safe2): # of improved

water sources:3 20,668 (% functional): (78%)

24326 # of washrooms:

Location Map



Water Access

Three most commonly identified types of water points, by functionality:

| 80% | Handpump / tube well | 74% | 26% | |
|-----|----------------------|-----|-----|----------------|
| 15% | Water tank | 94% | 6% | Functional |
| 5% | Tapstand | 86% | 14% | Non-functional |

| Key sectoral standards: | Target | Current Round | Achievement |
|---|----------|----------------------|-------------|
| # of people per functional improved water source | max. 250 | 55 | |
| % of shelters with at least 1 functional improved water source³ within 200m | 100% | 100% | |
| % of functional improved water sources with no latrine within 10m | 100% | 47% | |

Sanitation

Latrine characteristics:

Functionality and safety



77% Functional (non-full) and safe² 23%

Non-functional and / or unsafe

Functionality



Safety



90% Safe²

10% Unsafe

Lighting



1% 99% With lights Without lights

| Key sectoral standards: | Target | Current Round | Achievement |
|---|---------|---------------|-------------|
| # of people per functional (non-full) and safe latrine ² | max. 20 | 27 | |
| # of people per functional (non-full) latrine | max. 20 | 25 | |
| # of people per safe latrine ² | max. 20 | 24 | |
| % of shelters with at least one functional and safe latrine ² block within 50m | 100% | 97% | |

Targets based on long term WASH Sector Standards / Indicators for the Rohingya response, Sphere Minimum Standards as well as Department of Public Health and Environment (DPHE) Minimum Standards. Minimum standard/indicator reached, 75%-99% minimum standard/indicator reached, 50-74% minimum standard/indicator reached, indicator reached, Less than 50% of minimum standard/indicator reached.



^{1.} REACH enumerators conducted a full sweep of all sites and camps (as per boundaries defined by ISCG) and used an Open Data Kit (ODK) form to log all key infrastructure observed during this sweep, with further details to be logged for WASH infrastructure.

details to be logged to what immestudents.

2. Safe refers to fully covered latrines (i.e. a latrine with four walls, a roof and a lockable door).

3. This includes handpumps / tube wells, tapstands and water tanks.