

# **WASH Site Profile - Camp 11**

Ukhia, Cox's Bazar, Bangladesh (May 2018) GPS Coordinates: 21.1828, 92.1557



#### **Summary**

This profile provides an overview of water, sanitation and hygiene (WASH) infrastructure within Camp 11 in Ukhia, Cox's Bazar. Primary data for the sixth round was collected between 22 April -12 May 2018.1 Findings should be considered indicative only. The full camp dataset is available on HDX.

#### **Site Overview Key WASH Infrastructure**

# of individuals:	34,167	# of latrines:	949
# of households:	8,327	(% functional and safe <sup>2</sup> ):	(78%)
# of shelters:	4,928	# of improved water sources: <sup>3</sup> (% functional):	473 (81%)
# of individuals			

# of washrooms:

529

## **Location Map**



## Water Access

Three most commonly identified types of water points, by functionality:

per shelter:

95%	Handpump / tube well	78%	22%	
3%	Water tank	100%	0%	Functional
1%	Tapstand	100%	0%	Non-functional

6.9

Key sectoral standards:	Target	<b>Current Round</b>	Achievement
# of people per functional improved water source <sup>3</sup>	max. 250	90	
% of shelters with at least 1 functional improved water source <sup>3</sup> within 200m	100%	100%	
% of functional improved water source with no latrine within 10m	100%	53%	

Safety

# Sanitation

## Latrine characteristics:



#### **Functionality**





### Lighting



Key sectoral standards:	Target	Current Round	Achievement
# of people per functional (non-full) and safe latrine <sup>2</sup>	max. 20	46	
# of people per functional (non-full) latrine	max. 20	41	
# of people per safe latrine <sup>2</sup>	max. 20	44	
% of shelters with at least one functional and safe latrine <sup>2</sup> block within 50m	100%	98%	

Targets based on long term WASH Sector Standards / Indicators for the Rohingya response, Sphere Minimum Standards as well as Department of Public Health and Environment (DPHE) Minimum Standards. Minimum standard/indicator reached, 75-99% of the minimum standard reached, or within 25% of minimum standard reached, 50-74% of the minimum standard reached, or within 26-50% of minimum standard reached, 1 cash than 50% of minimum standard reached, or within greater than 50% of minimum standard reached.

3. This includes handpumps / tubewells, tapstands and water tanks.

<sup>1</sup> REACH enumerators conducted a full sweep of all sites and camps (as per boundaries defined by ISCG) and used a Kobo form to log all key infrastructure observed during this sweep.

<sup>2 &#</sup>x27;Safe' refers to fully covered latrines (i.e. a latrine with four walls, a roof and a lockable door).




# **WASH Site Profile - Camp 11**

Ukhia, Cox's Bazar, Bangladesh (May 2018) GPS Coordinates: 21.1828, 92.1557





## **Water Access**





# **WASH Site Profile - Camp 11**

Ukhia, Cox's Bazar, Bangladesh (May 2018) GPS Coordinates: 21.1828, 92.1557





### **Sanitation**

