



● Latrines Block	● Hand Pump - Tubewell	● Clinic
○ Washrooms	● Water Tap	● Nutrition Center
○ Desludging Tank	● Water Tank	● Child Friendly Space
○ Bio-gas Digester	● Unimproved well	● Women Friendly Space
■ Latrines Block (Non functioning)	● Unimproved Water Source	● Learning Center / Madrassah
■ Washrooms (Non functioning)*	● Water Tap (Non functioning)*	● Shop(s)
● Open Defecation Area	● Hand Pump - Tubewell (Non functioning)*	● Distribution Center
		● Mosque
		● Street Light

Site Boundary

Shelter Footprints (as of 26th October)

River

Primary Footpaths

Data Sources:
Camp Infrastructure - REACH
Site Boundaries - REACH / OCHA ROAP
Shelter Footprints - REACH / UNOSAT
Satellite Imagery: Pleiades from 26 October 2017
Copyright: CNES
Source: Airbus DS

Coordinate System: WGS 1984 UTM Zone 46N
Projection: Transverse Mercator
File: reach_bgd_map_coxsbazar_unchiprang_infrastructure_02122017_a1

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the REACH partners, associated, donors mentioned on this map.

*Due to missing information in data collected by enumerators, the number of non-functioning facilities may be higher than indicated.