WASH Sector Cox's Bazar

:$6+ 6LWH 3URÀOH &DPS (

Ukhia, Cox's Bazar, Bangladesh (October 2018)

GPS Coordinates: 92.1556, 21.2165

6XPPDU\

This profile provides an overview of water, sanitation and hygiene (WASH) infrastructure within Camp 01E in Ukhia, Cox's Bazar. Primary data for this round was collected from 17 September to 22 October 2018[1]. Findings should be considered indicative only. Full camp dataset is available on HDX.

Site Overview

# of individuals:	39,481
# of households:	9,086
# of shelters:	5,222
# of individuals SHU VKHOWHU	8

Key WASH Infrastructure

# of latrines:	1,543
(% functional and safe[2]):	(83%)
RI LPSURYHG water sources[3]:	882
(% functional):	(82%)
RI ZDVKURRPV	770

/RFDWLRQ 0DS



Water Access

7KUHH PRVW FRPPRQO\ LGHQWLÀHG W\SHV RI ZDWHU SRLQWV

70%	Handpump / tube well	79%		21%
24%	Water tank	90%		10%
5%	Tapstand	83%		17%

Functional

1RQ IXQFWLRQDO

Key sectoral standards:

	Target	Current Round	$FKLHYHPHQW
# of people per functional improved water source	PD[	54	
% of shelters with at least 1 functional improved water source[3] within 200m	100%	100%	
% of functional improved water sources with no latrine within 10m	100%	49%	

Sanitation

Latrine characteristics:

Functionality and safety

83% Functional (non-full) and safe[2]

17% Non-functional and / or unsafe

Functionality

87% Functional (non-full)

13% Non-functional

Safety

97% Safe[2]

3% Unsafe

Lighting



1% With lights

99% Without lights

Key sectoral standards:

	Target	Current Round	$FKLHYHPHQW
# of people per functional (non-full) and safe latrine[2]	PD[	31	
# of people per functional (non-full) latrine	PD[	29	
# of people per safe latrine[2]	PD[	28	
% of shelters with at least one functional and safe latrine[2] block within 50m	100%	100%	

Targets based on long term WASH Sector Standards / Indicators for the Rohingya response, Sphere Minimum Standards as well as Department of Public Health and Environment (DPHE) Minimum Standards. Minimum standard/indicator reached, 75%-99% minimum standard/indicator reached, 50-74% minimum standard/indicator reached, Less than 50% of minimum standard/indicator reached.

1. REACH enumerators conducted a full sweep of all sites and camps (as per boundaries defined by ISCG) and used an Open Data Kit (ODK) form to log all key infrastructure observed during this sweep, with further details to be logged for WASH infrastructure.
2. Safe refers to fully covered latrines (i.e. a latrine with four walls, a roof and a lockable door).
3. This includes handpumps / tube wells, tapstands and water tanks.