


IRAQ - Kirkuk Governorate - Laylan 2 Camp

Tent Condition - Updated 23 January 2017



Density of Sample Tents Experiencing Flooding



Sample Tent Location


-  Tents with Secondary Cover
-  Tents without Secondary Cover

Camp Infrastructure

-  Fence
-  Sector (A - N)
-  Office / Facility
-  Entrance
-  Health
-  Borehole (2)
-  Water Tank (2)
-  Tap Stand (51)

Layout of 16 Tents

-  Tent
-  Latrine
-  Kitchen
-  Shower



0% do not utilize secondary cover

6% experience flooding

0% do not have concrete base

Note:

Based on 104 Samples taken within the camp, following the same methodology as the camp profiling exercise, the assessment used household level sampling with a 95% confidence level and 10% margin of error.

GPS Coordinates of Camp Location:

Longitude: 44° 31' 45.155" E
(44.529210)
Latitude: 35° 19' 46.463" N
(35.329573)

Thematic Data: - 23/01/2017 REACH
Administrative boundaries: GADM
Background imagery: Airbus - Pleiades
- 29/07/2016
Projection: WGS 1984 UTM Zone 38N
Contact : iraq@reach-initiative.org
File: IRQ_MAP_IDP_Laylan2_
Tentcondition_24Apr2017

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the REACH partners, associates or donors mentioned on this map.



Scale 1: 500
0 15 30 60 90 120 Meters

