



1stVersion

As of 10th Optober 2011













Working map produced by REACH for humanitarian relief purposes only.

ite: Data contained on this map does not represent the opinion of any government or poblical body.

Legend

Neighborhood (Mantikas)

Technical Shelter Assessment Category of damage

- Light Damages
- Medium Damages
- Heavy Damages
- 100% Damaged House to rebuilt

ACTED/REACH Mapping Unit

High Resolution Imagery
Image acquisition date - 11 August 201
Satellite image copyright - DigitalGlobe 201
Image processing - UNTAR/UNDSA'
Low Resolution Imagery

Image acquisition date - 9 April 2006 Satellite image copyright - Google Earth Pro 2011 Shelter assessment - REACH Field Teams Mantikas - REACH Field Team

ors:

benghazi reach@acted.o

Reference Id: CH.A.D.UNHCRass

