

## **WASH Site Profile - Camp 8W**

Ukhia, Cox's Bazar, Bangladesh (May 2018) GPS Coordinates: 21.1968, 92.1541



#### **Summary**

This profile provides an overview of water, sanitation and hygiene (WASH) infrastructure within Camp 8W in Ukhia, Cox's Bazar. Primary data for the sixth round was collected between 22 April - 12 May 2018.¹ Findings should be considered indicative only. The full camp dataset is available on HDX.

#### Site Overview Key WASH Infrastructure

5.7

# of individuals: 28,325 # of latrines: 1,393

# of households: 6,748 safe²): (84%)

# of shelters: 4,983 # of improved water sources:³ 577

(% functional): (83%)

(% functional): (83%)
# of washrooms: 487



#### **Water Access**

Three most commonly identified types of water points, by functionality:

per shelter:

# of individuals

83%	Handpump / tube well	81%	19%	
16%	Water tank	99%	1%	Functional
1%	Tapstand	75%	25%	Non-functional

Key sectoral standards:	Target	<b>Current Round</b>	Achievement
# of people per functional improved water source <sup>3</sup>	max. 250	59	
% of shelters with at least 1 functional improved water source³ within 200m	100%	100%	
% of functional improved water source with no latrine within 10m	100%	34%	

## 专

## Sanitation

### Latrine characteristics:

Functionality and safety

84% Functional (non-full) and safe²16% Non-functional and / or unsafe

Functionality



Safety



89% Safe²11% Unsafe

Lighting



**0%** 100%

With lights
Without lights

Key sectoral standards:	Target	<b>Current Round</b>	Achievement
# of people per functional (non-full) and safe latrine <sup>2</sup>	max. 20	24	
# of people per functional (non-full) latrine	max. 20	22	
# of people per safe latrine <sup>2</sup>	max. 20	23	
% of shelters with at least one functional and safe latrine <sup>2</sup> block within 50m	100%	99%	

Targets based on long term WASH Sector Standards / Indicators for the Rohingya response, Sphere Minimum Standards as well as Department of Public Health and Environment (DPHE) Minimum Standards. Minimum standard/indicator reached, 75-99% of the minimum standard reached, or within 25% of minimum standard reached, or within 26-50% of minimum standard reached, Less than 50% of minimum standard reached, or within greater than 50% of minimum standard reached.

3. This includes handpumps / tubewells, tapstands and water tanks



<sup>1</sup> REACH enumerators conducted a full sweep of all sites and camps (as per boundaries defined by ISCG) and used a Kobo form to log all key infrastructure observed during this sweep.

<sup>2 &#</sup>x27;Safe' refers to fully covered latrines (i.e. a latrine with four walls, a roof and a lockable door).




# **WASH Site Profile - Camp 8W**

Ukhia, Cox's Bazar, Bangladesh (May 2018) GPS Coordinates: 21.1968, 92.1541



### **Water Access**





# **WASH Site Profile - Camp 8W**

Ukhia, Cox's Bazar, Bangladesh (May 2018) GPS Coordinates: 21.1968, 92.1541





#### **Sanitation**

