

WASH Site Profile - Camp 02E

Ukhia, Cox's Bazar, Bangladesh (August 2018) GPS Coordinates: 92.1643, 21.2078



Summary

This profile provides an overview of water, sanitation and hygiene (WASH) infrastructure within Camp 02E in Ukhia, Cox's Bazar. Primary data for this round was collected from 29th July to 29th August 2018.1 Findings should be considered indicative only. Full camp dataset is available on HDX.

Site Overview

of individuals: 28,789 # of households: 6,923

of shelters: 4,437

of individuals per shelter:

Key WASH Infrastructure

| # of latrines: | 857 |
|---|----------------|
| (% functional and safe ²): | (80%) |
| # of improved water sources: ³ (% functional): | 1,188 (90%) |
| # of washrooms: | 292 |

Location Map



Water Access

Three most commonly identified types of water points, by functionality:

| 37% | Handpump / tube well | 75% | 25% | Functional |
|-----|----------------------|-----|-----|----------------|
| 61% | Water tank | 99% | 1% | Functional |
| 2% | Tapstand | 90% | 10% | Non-functional |

6

| Key sectoral standards: | Target | Current Round | Achievement |
|---|----------|----------------------|-------------|
| # of people per functional improved water source | max. 250 | 27 | |
| % of shelters with at least 1 functional improved water source³ within 200m | 100% | 100% | |
| % of functional improved water sources with no latrine within 10m | 100% | 27% | |

Safety

Sanitation

Latrine characteristics: **Functionality and safety**

80%

Functional (non-full) and safe² 20% Non-functional and / or unsafe

Functionality





Lighting



| Key sectoral standards: | Target | Current Round | Achievement |
|---|---------|----------------------|-------------|
| # of people per functional (non-full) and safe latrine ² | max. 20 | 42 | |
| # of people per functional (non-full) latrine | max. 20 | 39 | |
| # of people per safe latrine ² | max. 20 | 38 | |
| % of shelters with at least one functional and safe latrine ² block within 50m | 100% | 97% | |

Targets based on long term WASH Sector Standards / Indicators for the Rohingya response, Sphere Minimum Standards as well as Department of Public Health and Environment (DPHE) Minimum Standards. Minimum standard/indicator reached, 75%-99% minimum standard/indicator reached, 50-74% minimum standard/indicator reached, indicator reached, Less than 50% of minimum standard/indicator reached.

^{1.} REACH enumerators conducted a full sweep of all sites and camps (as per boundaries defined by ISCG) and used an Open Data Kit (ODK) form to log all key infrastructure observed during this sweep, with further REACH endinerators conducted a four sweep or all sites and camps (as per boundaries de details to be logged for WASH infrastructure.
Safe refers to fully covered latrines (i.e. a latrine with four walls, a roof and a lockable door).
This includes handpumps / tube wells, tapstands and water tanks.


WASH Site Profile - Camp 02E

Ukhia, Cox's Bazar, Bangladesh (August 2018) GPS Coordinates: 92.1643, 21.2078





Water Access



Unimproved Water Sources

The boundaries and names used on this map do not imply official endorsement or acceptance by the United Nations



WASH Site Profile - Camp 02E

Ukhia, Cox's Bazar, Bangladesh (August 2018) GPS Coordinates: 92.1643, 21.2078





Sanitation

