

WASH Site Profile - Kutupalong MS

Ukhiya Cox's Bazar, Bangladesh (November 2017) **GPS Coordinates:**



Summary

This profile provides an overview of water, sanitation and hygiene (WASH) infrastructure Kutupalong MS in Ukhiya, Cox's Bazar. Primary data represents present as of 2017.1 Findings infrastructure î 9 November should be considered indicative only.

Site Information Key WASH Infrastructure

22898

of households:

of latrines # of individuals: 113688 (80%)(% functional): # of shelters: 7180 % of safe latrines2: 86% # of individuals 16 # of handpumps 455 (79%) per shelter:

(% functional):


of washrooms: 1343

Location Map





Access to Water



Three most commonly identified types of water points, by functionality

88% Handpump/ tubewell	79%	21%	
6% Tapstand	74%	74%	Functioning Not functioning
4% Water tank	96%	4%	

Key sectoral achievements

Targets based on WASH Sector Standards/Indicators for the Rohingya response, Sphere Minimum Standards/Indicators as well as Department of Public Health and Environment (DPHE) Minimum Standards/Indicators Minimum standard/indicator reached, 75%-99% minimum standard/indicator reached, ● 50-74% minimum standard/indicator reached, ● Less than 50% of minimum standard/indicator reached

	Target	Previous Round	Current Round	Achievement
# of people per functioning hand pump	max. 500 ³	197	250	
% of shelters within 200 metres of a functioning hand pump ⁴	100%	100%	100%	

¹Primary data for this round was collected between 20 October and 9 November 2017. REACH enumerators conducted a full sweep of all sites and camps (as per boundaries defined by ISCG) and used an Open Data Kit (ODK) form to log all key infrastructure observed during this sweep, with further details to be logged for WASH infrastructure. ²Safe refers to fully covered latrines (i.e. a latrine with four walls, a roof and a door) ³This target is based on standards for the long term (6 months+), for the immediate and medium phase (0-6 months) it is 500. ⁴The distance is based on standards for the long term (6 months+), for the immediate phase (0-3 months) it is 750 metres and for the medium phase (3-6 months) 500 metres.






WASH Cluster WASH Site Profile - Kutupalong MS





Sanitation



Latrine characteristics

% of functional/ non-functional latrines



80% functional non full latrines20% non/functional latrines

% of safe/ unsafe latrines:



86% Safe (roof, door, wall)14% Unsafe





1% With lights99% Without lights

Key sectoral achievements

Targets based on WASH Sector Standards/Indicators for Rohingya response, Sphere Minimum Standards/Indicators as well as DPHE Minimum Standards/Indicators • Minimum standard/indicator reached, • 75%-99% minimum standard/indicator reached, • 50-74% minimum standard/indicator reached, • Less than 50% of minimum standard/indicator reached

2000 than 00 /0 of minimal standard/indicator rodoriod				
	Target	Previous Round	Current Round	Achievement
# of people per functional (non-full) latrine	max. 50 ⁴	95	106	
# of people per safe latrine	N/A	76	22	N/A
% of shelters within 50 meters to a functional (non-full) latrine	100%	84%	96%	
% of latrines that are at least 10 meters away from a water point	100%	67%	72%	

⁴This target is based on standards for the long term (6 months +), for the immediate phase (0-3 months) it is 100 and for the medium phase (3-6 months) 75.



