

WASH Site Profile - Camp 04

Ukhia, Cox's Bazar, Bangladesh (August 2018) GPS Coordinates: 92.1429, 21.2082



Summary

This profile provides an overview of water, sanitation and hygiene (WASH) infrastructure within Camp 04 in Úkhia, Cox's Bazar. Primary data for this round was collected from 29th July to 29th August 2018.1 Findings should be considered indicative only. Full camp dataset is available on HDX.

Site Overview

of individuals: 30,394 # of households: 7,472

of shelters: 7,894

of individuals per shelter:

Key WASH Infrastructure

of latrines: 2,135 (% functional and safe2): (77%)# of improved water sources:3 1,126 (% functional): (81%)# of washrooms: 1,042

Location Map



Water Access

Three most commonly identified types of water points, by functionality:

69%	Handpump / tube well	75%	25%	Functional
29%	Water tank	94%	6%	Functional
2%	Tapstand	89%	11%	Non-functional

4

Key sectoral standards:	Target	Current Round	Achievement
# of people per functional improved water source	max. 250	33	
% of shelters with at least 1 functional improved water source³ within 200m	100%	100%	
% of functional improved water sources with no latrine within 10m	100%	51%	

Sanitation

Latrine characteristics:

Functionality and safety



77% Functional (non-full) and safe² 23%

Non-functional and / or unsafe



85% Functional (non-full)

15% Non-functional

Safety



90% Safe²

10% Unsafe

Lighting



With lights

1% 99% Without lights

Key sectoral standards:	Target	Current Round	Achievement
# of people per functional (non-full) and safe latrine ²	max. 20	18	
# of people per functional (non-full) latrine	max. 20	17	
# of people per safe latrine ²	max. 20	16	
% of shelters with at least one functional and safe latrine ² block within 50m	100%	100%	

Targets based on long term WASH Sector Standards / Indicators for the Rohingya response, Sphere Minimum Standards as well as Department of Public Health and Environment (DPHE) Minimum Standards. Minimum standard/indicator reached, 75%-99% minimum standard/indicator reached, 50-74% minimum standard/indicator reached, indicator reached, Less than 50% of minimum standard/indicator reached.




^{1.} REACH enumerators conducted a full sweep of all sites and camps (as per boundaries defined by ISCG) and used an Open Data Kit (ODK) form to log all key infrastructure observed during this sweep, with further REACH endinerators conducted a four sweep or all sites and camps (as per boundaries de details to be logged for WASH infrastructure.
Safe refers to fully covered latrines (i.e. a latrine with four walls, a roof and a lockable door).
This includes handpumps / tube wells, tapstands and water tanks.

WASH Site Profile - Camp 04

Ukhia, Cox's Bazar, Bangladesh (August 2018) GPS Coordinates: 92.1429, 21.2082



Water Access



official endorsement or acceptance by the United Nations



WASH Site Profile - Camp 04

Ukhia, Cox's Bazar, Bangladesh (August 2018) GPS Coordinates: 92.1429, 21.2082



3

Sanitation

