




Thematic Data: 10 April 2016 - REACH
Administrative boundaries: GADM
Background Imagery: 04/07/2015

Coordinate System: WGS 1984 UTM Zone 38N
File: IRQ_Map_IDP_Khanke_BlockedToilets_8June2016
Contact: reach.mapping@impact-initiatives.org

Note: Data, designations and boundaries contained on this map are not warranted to error-free and do not imply acceptance by the REACH partners, associated, donors mentioned on this map.




Overflowing Toilets (%) in Housing Blocks and Communal Buildings



Thematic Data: 10 April 2016 - REACH
Administrative boundaries: GADM
Background Imagery: 04/07/2015

Coordinate System: WGS 1984 UTM Zone 38N
File: IRQ_Map_IDP_Khanke_OverflowingToilets_8June2016
Contact: reach.mapping@impact-initiatives.org


Note: Data, designations and boundaries contained on this map are not warranted to error-free and do not imply acceptance by the REACH partners, associated, donors mentioned on this map.



Thematic Data: 10 April 2016 - REACH
Administrative boundaries: GADM
Background Imagery: 04/07/2015

Coordinate System: WGS 1984 UTM Zone 38N
File: IRQ_Map_IDP_Khanke_NonFunctioningShowers_8June2016
Contact: reach.mapping@impact-initiatives.org

Note: Data, designations and boundaries contained on this map are not warranted to error-free and do not imply acceptance by the REACH partners, associated, donors mentioned on this map.



Thematic Data: 10 April 2016 - REACH
Administrative boundaries: GADM
Background Imagery: 04/07/2015

Coordinate System: WGS 1984 UTM Zone 38N
File: IRQ_Map_IDP_Khanke_NonFunctioningTaps_8June2016
Contact: reach.mapping@impact-initiatives.org

Note: Data, designations and boundaries contained on this map are not warranted to error-free and do not imply acceptance by the REACH partners, associated, donors mentioned on this map.