WASH Sector Cox's Bazar

WASH Site Profile - Jadimura
Teknaf, Cox's Bazar, Bangladesh (May 2018)
GPS Coordinates: 20.9381, 92.2602

Summary

This profile provides an overview of water, sanitation and hygiene (WASH) infrastructure within Jadimura in Teknaf, Cox's Bazar. Primary data for the sixth round was collected between 22 April - 12 May 2018.[1] Findings should be considered indicative only. The full camp dataset is available on HDX.

Site Overview

# of individuals:	25,274
# of households:	5,700
# of shelters:	808
# of individuals per shelter:	31.3

Key WASH Infrastructure

# of latrines:	482
(% functional and safe[2]):	(82%)
# of improved water sources:[3] (% functional):	94 (88%)
# of washrooms:	224

Location Map

Ukhia — MYANMAR — Teknaf

Water Access

Three most commonly identified types of water points, by functionality:

%	Type	Functional	Non-functional
41%	Handpump / tube well	71%	29%
31%	Water tank	100%	0%
28%	Tapstand	100%	0%

- Functional
- Non-functional

Key sectoral standards:

	Target	Current Round	Achievement
# of people per functional improved water source[3]	max. 250	305	🟢
% of shelters with at least 1 functional improved water source[3] within 200m	100%	98%	🟢
% of functional improved water source with no latrine within 10m	100%	31%	🔴

Sanitation

Latrine characteristics:

Functionality and safety

- 82% Functional (non-full) and safe[2]
- 18% Non-functional and / or unsafe

Functionality

- 94% Functional (non-full)
- 6% Non-functional

Safety

- 84% Safe[2]
- 16% Unsafe

Lighting

- 0% With lights
- 100% Without lights

Key sectoral standards:

	Target	Current Round	Achievement
# of people per functional (non-full) and safe latrine[2]	max. 20	64	🔴
# of people per functional (non-full) latrine	max. 20	56	🔴
# of people per safe latrine[2]	max. 20	62	🔴
% of shelters with at least one functional and safe latrine[2] block within 50m	100%	89%	🟢

Targets based on long term WASH Sector Standards / Indicators for the Rohingya response, Sphere Minimum Standards as well as Department of Public Health and Environment (DPHE) Minimum Standards. 🔵Minimum standard/indicator reached, 🟢75-99% of the minimum standard reached, or within 25% of minimum standard reached, 🟠50-74% of the minimum standard reached, or within 26-50% of minimum standard reached, 🔴Less than 50% of minimum standard reached, or within greater than 50% of minimum standard reached.

1 REACH enumerators conducted a full sweep of all sites and camps (as per boundaries defined by ISCG) and used a Kobo form to log all key infrastructure observed during this sweep.
2 'Safe' refers to fully covered latrines (i.e. a latrine with four walls, a roof and a lockable door).
3. This includes handpumps / tubewells, tapstands and water tanks.

ISCG
INTER SECTOR COORDINATION GROUP

For more information, please contact REACH:
bangladesh@reach-initiative.org

REACH
An initiative of IMPACT Initiatives ACTED and UNOSAT

1

WASH Sector
Cox's Bazar

Water Access

Nayapara EXP

Area outside ISCG camp boundaries

Metres

| 0 | 125 | 250 | 500 | 750 | 1.000 |

	Functioning		Non-functioning	
Hand pump / tubewell	●	27	●	11
Tapstand	▣	26	▣	0
Well	▣	0	▣	3
Water tank	●	29	●	0
Unimproved water source	✕	14	✕	0

Shelter

Camp boundary

River

The boundaries and names used on this map do not imply official endorsement or acceptance by the United Nations

Ukhia
MYANMAR
Teknaf

INTER SECTOR
COORDINATION
GROUP

REACH
An initiative of
IMPACT Initiatives
ACTED and UNOSAT

WASH Site Profile - Jadimura
Teknaf, Cox's Bazar, Bangladesh (May 2018)
GPS Coordinates: 20.9381, 92.2602

🚰 Sanitation

Nayapara EXP

Area outside ISCG camp boundaries

Metres

| 0 | 125 | 250 | 500 | 750 | 1.000 |

	Functioning		Non-functioning	
Latrines	●	304	●	17
WASH rooms	■	188		

Shelter

Camp boundary

River

Ukhia · MYANMAR

Teknaf

The boundaries and names used on this map do not imply official endorsement or acceptance by the United Nations

---