



- | | | | | | |
|---|----------------------------------|---|---|---|-----------------------------|
| ● | Latrines Block | ● | Hand Pump - Tubewell | 🏥 | Clinic |
| ○ | Washrooms | 🚰 | Water Tap | 🍲 | Nutrition Center |
| ○ | Desludging Tank | 💧 | Water Tank | 👶 | Child Friendly Space |
| ○ | Bio-gas Digester | 🚰 | Unimproved well | 👩 | Women Friendly Space |
| 🚽 | Latrines Block (Non functioning) | 🚰 | Unimproved Water Source | 📖 | Learning Center / Madrassah |
| 🚽 | Washrooms (Non functioning)* | 🚰 | Water Tap (Non functioning)* | 🛍 | Shop(s) |
| + | Open Defecation Area | 🚰 | Hand Pump - Tubewell (Non functioning)* | 🏪 | Distribution Center |
| | | | | 🕌 | Mosque |
| | | | | 💡 | Street Light |

Zone Boundary Shelter Footprints (as of 26th October) River Primary Footpaths

Data Sources:
Camp Infrastructure - REACH
Site Boundaries - REACH / OCHA ROAP
Shelter Footprints - REACH / UNOSAT
Satellite Imagery: Pleiades from 26 October 2017
Copyright: CNES
Source: Airbus DS

Coordinate System: WGS 1984 UTM Zone 46N
Projection: Transverse Mercator
File:
reach_bgd_map_coxsbazar_kutupalongZA_infrastructure_02122017_a1
Note: Data, designations and boundaries contained on this map are not
warranted to be error-free and do not imply acceptance by the REACH
partners, associated, donors mentioned on this map.

*Due to missing information in data collected by enumerators, the number of non-functioning facilities may be higher than indicated.