

WASH Site Profile - Camp 24 (Leda)

Teknaf, Cox's Bazar, Bangladesh (July 2018) GPS Coordinates: 20.9717, 92.2480



Summary

This profile provides an overview of water, sanitation and hygiene (WASH) infrastructure within Camp 24 (Leda) in Teknaf, Cox's Bazar. Primary data for this round was collected from 29th May to 22nd July 2018.1 Findings should be considered indicative only. Full camp dataset is available on HDX.

Site Overview

of individuals: 33,731 # of households: 7,804

of shelters: 3,966 # of individuals

Key WASH Infrastructure

of latrines: 1,048 (% functional and safe2): (78%)# of improved water sources:3 289 (% functional): (88%)563 # of washrooms:

Location Map



Water Access

Three most commonly identified types of water points, by functionality:

per shelter:

36%	Handpump / tube well	80%	20%	
39%	Water tank	95%	5%	Functional
20%	Tapstand	88%	12%	Non-functional

8.5

Key sectoral standards:	Target	Current Round	Achievement
# of people per functional improved water source	max. 250	132	
% of shelters with at least 1 functional improved water source³ within 200m	100%	100%	
% of functional improved water sources with no latrine within 10m	100%	52%	

Sanitation

Latrine characteristics:

Functionality and safety



78% Functional (non-full) and safe² 22%

Non-functional and / or unsafe

Functionality



Safety



85% Safe²

15% Unsafe

Lighting



0% 100% With lights Without lights

Key sectoral standards:	Target	Current Round	Achievement
# of people per functional (non-full) and safe latrine ²	max. 20	41	
# of people per functional (non-full) latrine	max. 20	36	
# of people per safe latrine ²	max. 20	39	
% of shelters with at least one functional and safe latrine² block within 50m	100%	94%	

Targets based on long term WASH Sector Standards / Indicators for the Rohingya response, Sphere Minimum Standards as well as Department of Public Health and Environment (DPHE) Minimum Standards. Minimum standard/indicator reached, 75%-99% minimum standard/indicator reached, 50-74% minimum standard/indicator reached, indicator reached, Less than 50% of minimum standard/indicator reached.



^{1.} REACH enumerators conducted a full sweep of all sites and camps (as per boundaries defined by ISCG) and used an Open Data Kit (ODK) form to log all key infrastructure observed during this sweep, with further


REACH endinerators conducted a four sweep or all sites and camps (as per boundaries de details to be logged for WASH infrastructure.
 Safe refers to fully covered latrines (i.e. a latrine with four walls, a roof and a lockable door).
 This includes handpumps / tube wells, tapstands and water tanks.

WASH Site Profile - Camp 24 (Leda)

Teknaf, Cox's Bazar, Bangladesh (July 2018)
GPS Coordinates: 20.9717, 92.2480



Water Access



The boundaries and names used on this map do not imply official endorsement or acceptance by the United Nations

WASH Site Profile - Camp 24 (Leda)

Teknaf, Cox's Bazar, Bangladesh (July 2018)
GPS Coordinates: 20.9717, 92.2480





Sanitation

