

## **WASH Site Profile - Camp 8E**

Ukhia, Cox's Bazar, Bangladesh (May 2018) GPS Coordinates: 21.1956, 92.165



#### **Summary**

This profile provides an overview of water, sanitation and hygiene (WASH) infrastructure within Camp 8E in Ukhia, Cox's Bazar. Primary data for the sixth round was collected between 22 April -12 May 2018.1 Findings should be considered indicative only. The full camp dataset is available on HDX.

#### Site Overview

# of individuals: 34,990 # of latrines: 868 (% functional and safe2): # of households: 8,260 (85%)# of improved water sources:3 432 # of shelters: 4,247

(% functional): (91%)520 # of washrooms:

**Key WASH Infrastructure** 

## **Location Map**



### Water Access

Three most commonly identified types of water points, by functionality:

per shelter:

# of individuals

85%	Handpump / tube well	88%	12%	
8%	Water tank	100%	0%	Functional
7%	Tapstand	90%	10%	Non-functional

8.2

Key sectoral standards:	Target	<b>Current Round</b>	Achievement
# of people per functional improved water source <sup>3</sup>	max. 250	89	
% of shelters with at least 1 functional improved water source³ within 200m	100%	100%	
% of functional improved water source with no latrine within 10m	100%	36%	

**Functionality** 

Lighting

Safety

## Sanitation

### Latrine characteristics: **Functionality and safety**



Functional (non-full) and safe2 Non-functional and / or unsafe

### 90% Functional (non-full) 10% Non-functional





Key sectoral standards:	Target	<b>Current Round</b>	Achievement
# of people per functional (non-full) and safe latrine <sup>2</sup>	max. 20	47	
# of people per functional (non-full) latrine	max. 20	45	
# of people per safe latrine <sup>2</sup>	max. 20	44	
% of shelters with at least one functional and safe latrine <sup>2</sup> block within 50m	100%	91%	

Targets based on long term WASH Sector Standards / Indicators for the Rohingya response, Sphere Minimum Standards as well as Department of Public Health and Environment (DPHE) Minimum Standards. Minimum standard/indicator reached, 75-99% of the minimum standard reached, or within 25% of minimum standard reached, 50-74% of the minimum standard reached, or within 26-50% of minimum standard reached, 1 cash than 50% of minimum standard reached, or within greater than 50% of minimum standard reached.

<sup>1</sup> REACH enumerators conducted a full sweep of all sites and camps (as per boundaries defined by ISCG) and used a Kobo form to log all key infrastructure observed during this sweep.

<sup>2 &#</sup>x27;Safe' refers to fully covered latrines (i.e. a latrine with four walls, a roof and a lockable door).

<sup>3.</sup> This includes handpumps / tubewells, tapstands and water tanks




# **WASH Site Profile - Camp 8E**

Ukhia, Cox's Bazar, Bangladesh (May 2018) GPS Coordinates: 21.1956, 92.165



## **Water Access**





# **WASH Site Profile - Camp 8E**

Ukhia, Cox's Bazar, Bangladesh (May 2018) GPS Coordinates: 21.1956, 92.165





## **Sanitation**

