



- | Water                       | Sanitation           | Other                       |                         |
|-----------------------------|----------------------|-----------------------------|-------------------------|
| Well                        | Desludging Tank      | Distribution Center         | Footpath; Main Path     |
| Water Source                | Biogas Digester      | Clinic                      | Main Road; Vehicle Road |
| Water Tank                  | Open Defecation Area | Learning Center / Madrassah | Shelter Footprints      |
| Water Tap                   | Latrine              | Nutrition Center            | River; Water Body       |
| Tube Well                   | Washroom             | Mosque                      | Site Boundary           |
| Tube Well (non functioning) |                      | Child Friendly Space        |                         |
|                             |                      | Women Friendly Space        |                         |
|                             |                      | Shop(s)                     |                         |

**Data Sources:**  
Camp Infrastructure - REACH  
Site Boundaries - REACH / OCHA ROAP  
Shelter Footprints - REACH / UNOSAT

**Coordinate System:** WGS 1984 UTM Zone 46N  
**Projection:** Transverse Mercator  
**Contact:** reach.mapping@impact-initiatives.org  
**File:** reach\_bgd\_map\_coxsbazar\_Thangkhali\_infrastructure\_R3\_7012018\_a1.pdf

**Note:** Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the REACH partners, associated, donors mentioned on this map.

\*Due to missing information in data collected by enumerators, the number of non-functioning facilities may be higher than indicated.