





# MOZAMBIQUE - Beira City

## Pioneiros - Neighbourhood Damage Assessment - As of 26 March 2019


For Humanitarian Purposes Only  
Production date : 28 March 2019



Data sources:  
Damage sites - UNOSAT-REACH  
Beira Bairros - INGC  
Administrative Boundaries (0-3) - OCHA  
Satellite Imagery: WorldView-2 from 26 March 2019  
Copyright: ©DigitalGlobe 2019  
Source: US Dept of State Humanitarian Information Unit, NextView License

**Legend**

- Damaged Buildings
- Bairros



Coordinate System: GCS WGS 1984  
File: MOZ\_Map\_CycloneIdai\_Beira\_Damage\_Pioneiros\_28MAR2019  
Contact: reach.mapping@impact-initiatives.org

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the REACH partners, associated, donors mentioned on this map.

Funded by



Humanitarian Aid and Civil Protection

An initiative of  
IMPACT Initiatives  
ACTED and UNOSAT

**REACH**