## IRAQ - Duhok Governorate - Bersive 1 Camp Tent Condition - Updated 4 January 2017

For Humanitarian Purposes Only Production date: 11 April 2017

## Density of Sample Tents Experiencing Flooding

High : 3

Low : 1

## **Sample Tent Location**

- Tents with Secondary Cover
- ♠ Tents without Secondary Cover

## **Camp Infrastructure**

Fence

\_\_ Sector (A - P)

Office / Facility

**▶** Entrance

пеа

offic

Latrine (100

Shower (93

Dishwashing Area (32)

Laundry (17

Borehole (4)

Water Tank (1)

P Car Park

Bridge (6)

Rainwater Channel

Thematic Data: 4/1/2017 - REACH Administrative boundaries: GADM Background imagery: Airbus - Pleiades -7/7/2016

Projection: WGS 1984 UTM Zone 38N

Contact: iraq@reach-initiative.org

File:
IRQ\_Map\_IDP\_Bersive1\_Tentcondition\_111Apr2017

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the REACH partners, associates or donors mentioned on this map.



