
REPUBLIC OF SUDAN- Khartoum state Omdurman Building Damage Assessment of May 01, 2024







Building damage

- Destroyed
- Severely damaged
- Moderately damaged

Road

- Secondary
- Tertiary



Omdurman analysis extent (UNOSAT analysis Extend)



Neighborhood

Damage density



High

Satellite data (1): WorldView-3; Resolution: 30 cm Date: May 01, 2024 Copyright: ©2024 Maxar/DigitalGlobe

US Department of State, Humanitarian Information Unit, NextView License Neighborhood: Wikimapia and Mapcarta

Roads - OpenStreetMap

Damage Analysis : UNOSAT

Coordinate System:GCS WGS 1984 Contact: reach.mapping@impact-initiatives.org

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by REACH partners, associates or donors mentioned on this map.

The neighborhoods limits and names are indicative and intended for contextualization purpose