

WASH Site Profile - Camp 9

Ukhia, Cox's Bazar, Bangladesh (May 2018) GPS Coordinates: 21.19, 92.1603



Summary

This profile provides an overview of water, sanitation and hygiene (WASH) infrastructure within Camp 9 in Ukhia, Cox's Bazar. Primary data for the sixth round was collected between 22 April - 12 May 2018.1 Findings should be considered indicative only. The full camp dataset is available on HDX.

Site Overview Key WASH Infrastructure

# of individuals:	37,801	# of latrines:	710
# of households:	9,120	(% functional and safe ²):	(86%)
# of shelters: # of individuals	4,863	# of improved water sources: ³ (% functional):	724 (88%)

of washrooms:

Location Map

402



Water Access

Three most commonly identified types of water points, by functionality:

per shelter:

68%	Handpump / tube well	81%	19%	
30%	Water tank	92%	8%	Functional
3%	Tapstand	95%	5%	Non-functional


7.8

Key sectoral standards:	Target	Current Round	Achievement
# of people per functional improved water source ³	max. 250	60	
% of shelters with at least 1 functional improved water source³ within 200m	100%	100%	
% of functional improved water source with no latrine within 10m	100%	41%	

Safety

Sanitation

Latrine characteristics: **Functionality and safety**




Functionality



91% Safe² Unsafe

Lighting



Key sectoral standards:	Target	Current Round	Achievement
# of people per functional (non-full) and safe latrine ²	max. 20	62	
# of people per functional (non-full) latrine	max. 20	59	
# of people per safe latrine ²	max. 20	58	
% of shelters with at least one functional and safe latrine ² block within 50m	100%	97%	

Targets based on long term WASH Sector Standards / Indicators for the Rohingya response, Sphere Minimum Standards as well as Department of Public Health and Environment (DPHE) Minimum Standards. Minimum standard/indicator reached, 75-99% of the minimum standard reached, or within 25% of minimum standard reached, 50-74% of the minimum standard reached, or within 26-50% of minimum standard reached, 1 cash than 50% of minimum standard reached, or within greater than 50% of minimum standard reached.

3. This includes handpumps / tubewells, tapstands and water tanks.



¹ REACH enumerators conducted a full sweep of all sites and camps (as per boundaries defined by ISCG) and used a Kobo form to log all key infrastructure observed during this sweep.

^{2 &#}x27;Safe' refers to fully covered latrines (i.e. a latrine with four walls, a roof and a lockable door).




WASH Site Profile - Camp 9

Ukhia, Cox's Bazar, Bangladesh (May 2018)
GPS Coordinates: 21.19, 92.1603





Water Access





WASH Site Profile - Camp 9

Ukhia, Cox's Bazar, Bangladesh (May 2018)
GPS Coordinates: 21.19, 92.1603





Sanitation

