




- | | | | | | |
|--|---|--|---------------------|--|---|
| | Tubewell - Handpump (Functioning) | | Nutrition Centre | | Site Boundary (observed 27 September) |
| | Tubewell - Handpump (Not Functioning) | | Distribution Center | | Shelter Footprints (as of 21 September) |
| | Latrine - Functional (Not necessarily safe) | | Field Office | | Primary Footpaths |
| | Latrine - Full / Not Functional | | Market Area | | Main Road |
| | Wash Room | | Community center | | |
| | Unprotected Water Source | | Mosque | | |
| | Clinic | | | | |



Data Sources:
Site Boundaries - REACH / OCHA ROAP
Shelter Footprints - REACH / UNOSAT
Footpaths - REACH
Satellite Imagery: WorldView-1 from 21 September 2017
Copyright: ©2017 DigitalGlobe
Source: US Department of State, Humanitarian Information Unit, NextView License.
Coordinate System: GCS WGS 1984
File: reach_bgd_map_coxsbazar_hakimpara_infrastructure_28092017_a1
Contact: reach.mapping@impact-initiatives.org

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the REACH partners, associates or donors mentioned on this map.

