

# Syria - Southern Damascus

Shelter Damage Assessment as of 2nd April 2016

For Authorized Distribution Only - For Humanitarian Purposes Only  
Production Date: 16 November 2016



- Damage Zones 02.04.2016**
- Destroyed, High Density
  - Severe Damage, High Density
  - Moderate Damage, High Density
  - Destroyed, Low Density
  - Severe Damage, Low Density
  - Moderate Damage, Low Density

**5418** Buildings Damaged as of April 2016

**2073** destroyed

**1594** severely damaged

**1751** moderately damaged




Image copyright: DigitalGlobe, Imagery provided by: U.S. Department of State, Humanitarian Information Unit, NextView License - WV3 - Resolution 0.50 cm - Date: 02.04.2016  
Shelter Damage Assessment Data: UNOSAT/REACH  
Projection: WGS 1984 UTM Zone 37N  
File: REACH\_SYR\_Damage\_Assessment\_Southern\_Damascus\_2Apr16\_A3  
Contact: reach.mapping@impact-initiatives.org

Note: Data, designations and boundaries contained in this map are not warranted to be error-free and do not imply acceptance by the REACH partners, donors and associated persons mentioned in this map.

