


IRAQ - Erbil Governorate - Baharka Camp

Tent Condition - Updated 18 January 2017

Density of Sample Tents Experiencing Flooding





Sample Tent Location

- Tents with Secondary Cover
- Tents without Secondary Cover

Camp Infrastructure

- Fence
- Sector (A - G)
- Caravan Area
- Removed Blocks
- Office / Facility
- Entrance
- Gate
- Office
- Community Area
- Water Tank
- Borehole
- Generator

Layout of Single Block (Sector A, C, and E)



**GPS Coordinates
of Camp Location:**
Longitude: 43° 59' 39.655" E
(43.99352)
Latitude: 36° 17' 40.022" N
(36.29445)

Thematic Data: 18/01/2017 - REACH
Administrative boundaries: GADM
Background imagery: Digital globe -
GeoEye-1 - 23/05/2016
Projection: WGS 1984 UTM Zone 38N
Contact : iraq@reach-initiative.org
File:
IRQ_Map_IDP_Baharka_Tentcondition_11Apr2017

Note: Data, designations and boundaries
contained on this map are not warranted to be
error-free and do not imply acceptance by the
REACH partners, associates or donors
mentioned on this map.



Note:

Based on 40 Samples taken within
the camp, following the same
methodology as the camp profiling
exercise, the assessment used
household level sampling with a 95%
confidence level and 10% margin of
error.

5%
54%
0%

do not utilize secondary cover

experience flooding

do not have concrete base

Layout of Single Block (Sector B, D, and G)

