

# **WASH Site Profile - Camp 15**

Ukhia, Cox's Bazar, Bangladesh (May 2018) GPS Coordinates: 21.1605, 92.143



#### **Summary**

This profile provides an overview of water, sanitation and hygiene (WASH) infrastructure within Camp 15 in Ukhia, Cox's Bazar. Primary data for the sixth round was collected between 22 April -12 May 2018.1 Findings should be considered indicative only. The full camp dataset is available on HDX.

#### Site Overview

# of individuals: 46,666

# of households: 10,273

# of shelters: 9,870

# of individuals per shelter:

## **Key WASH Infrastructure**

# of latrines: 1,857 (% functional and safe2): (87%)

# of improved water sources:3 760 (% functional): (78%)

1034 # of washrooms:

### **Location Map**



### Water Access

Three most commonly identified types of water points, by functionality:

91%	Handpump / tube well	74%	26%	
7%	Water tank	95%	5%	Functional
2%	Tapstand	75%	25%	Non-functional

4.7

Key sectoral standards:	Target	<b>Current Round</b>	Achievement
# of people per functional improved water source <sup>3</sup>	max. 250	78	
% of shelters with at least 1 functional improved water source³ within 200m	100%	100%	
% of functional improved water source with no latrine within 10m	100%	50%	



## Sanitation

#### Latrine characteristics:

# **Functionality and safety**



87% Functional (non-full) and safe2 13%

Non-functional and / or unsafe

# **Functionality**



93% Functional (non-full)

Non-functional

Without lights

#### Safety Lighting



92% Safe<sup>2</sup> Unsafe

0% With lights

100%

Key sectoral standards:	Target	<b>Current Round</b>	Achievement
# of people per functional (non-full) and safe latrine <sup>2</sup>	max. 20	29	
# of people per functional (non-full) latrine	max. 20	27	
# of people per safe latrine <sup>2</sup>	max. 20	27	
% of shelters with at least one functional and safe latrine² block within 50m	100%	100%	

Targets based on long term WASH Sector Standards / Indicators for the Rohingya response, Sphere Minimum Standards as well as Department of Public Health and Environment (DPHE) Minimum Standards. Minimum standard/indicator reached, 75-99% of the minimum standard reached, or within 25% of minimum standard reached, 50-74% of the minimum standard reached, or within 26-50% of minimum standard reached, 1 cash than 50% of minimum standard reached, or within greater than 50% of minimum standard reached.

3. This includes handpumps / tubewells, tapstands and water tanks

<sup>1</sup> REACH enumerators conducted a full sweep of all sites and camps (as per boundaries defined by ISCG) and used a Kobo form to log all key infrastructure observed during this sweep.

<sup>2 &#</sup>x27;Safe' refers to fully covered latrines (i.e. a latrine with four walls, a roof and a lockable door).




# **WASH Site Profile - Camp 15**

Ukhia, Cox's Bazar, Bangladesh (May 2018) GPS Coordinates: 21.1605, 92.143



# **Water Access**





# **WASH Site Profile - Camp 15**

Ukhia, Cox's Bazar, Bangladesh (May 2018) GPS Coordinates: 21.1605, 92.143





## **Sanitation**

