WASH Site Profile - Chakmarkul

Teknaf, Cox's Bazar, Bangladesh (May 2018) GPS Coordinates: 21.1333, 92.1575



Summary

This profile provides an overview of water, sanitation and hygiene (WASH) infrastructure within Chakmarkul in Teknaf, Cox's Bazar. Primary data for the sixth round was collected between 22 April -12 May 2018.¹ Findings should be considered indicative only. The full camp dataset is available on <u>HDX</u>.

WASH Sector


Cox's Bazar

Site Overview **Key WASH Infrastructure** # of individuals: 11,967 # of latrines: 209 (% functional and safe²): # of households: 2,962 (92%) # of improved water sources:3 96 # of shelters: 1,824 (% functional): (88%) # of individuals 159 # of washrooms: per shelter: 6.6



Water Access

Three most commonly identified types of water points, by functionality:



Sanitation

Latrine characteristics:

Functionality and safety		unctionality			
	ctional (non-full) and safe ² -functional and / or unsafe	0	98% 2%	Functional (non-full) Non-functional	
Safety Lighting					
94% Safe 6% Unsa		0	0% 100%	With lights Without lights	
Key sectoral standards:		Target		Current Round	Achievement
# of people per functional (non-full) and safe latrine ²		max. 20		62	
# of people per functional (non-full) latrine		max. 20		58	
# of people per safe latrine ²		max. 20		61	
$\%$ of shelters with at least one functional and safe latrine $^2\text{block}$ within 50m		100%		92%	

Targets based on long term WASH Sector Standards / Indicators for the Rohingya response, Sphere Minimum Standards as well as Department of Public Health and Environment (DPHE) Minimum Standards. Minimum standard/indicator reached, Teached, Teached, Teached, or within 25% of minimum standard reached, or within 26-50% of minimum standard reached, or within 26-50% of minimum standard reached, Teached, Teached, Standards of minimum standard reached, or within 26-50% of minimum standard reached, or within greater than 50% of minimum standard reached.

1 REACH enumerators conducted a full sweep of all sites and camps (as per boundaries defined by ISCG) and used a Kobo form to log all key infrastructure observed during this sweep. 2 'Safe' refers to fully covered latrines (i.e. a latrine with four walls, a roof and a lockable door)

Safe' refers to fully covered latrines (i.e. a latrine with four walls, a roof and a lockable door).
This includes handpumps / tubewells, tapstands and water tanks.



INTER SECTOR COORDINATION GROUP

For more information, please contact REACH: bangladesh@reach-initiative.org




WASH Sector Cox's Bazar

WASH Site Profile - Chakmarkul

Teknaf, Cox's Bazar, Bangladesh (May 2018) GPS Coordinates: 21.1333, 92.1575



Water Access



For more information, please contact REACH: bangladesh@reach-initiative.org

2


WASH Sector Cox's Bazar

WASH Site Profile - Chakmarkul

Teknaf, Cox's Bazar, Bangladesh (May 2018) GPS Coordinates: 21.1333, 92.1575









For more information, please contact REACH: bangladesh@reach-initiative.org

REACH An initiative of IMPACT Initiatives ACTED and UNOSAT