

WASH Site Profile - Camp 10

Ukhia, Cox's Bazar, Bangladesh (October 2018) GPS Coordinates: 92.1542, 21.1897



Summary

This profile provides an overview of water, sanitation and hygiene (WASH) infrastructure within Camp 10 in Ukhia, Cox's Bazar. Primary data for this round was collected from 17 September to 22 October 2018.¹ Findings should be considered indicative only. Full camp dataset is available on HDX.

Site Overview Key WASH Infrastructure

of individuals:	32,667	# of latrines:	1,189
of households:	7,575	(% functional and safe ²):	(75%)
of shelters:	7,526	# of improved water sources: ³ (% functional):	1,434 (87%)

586 # of washrooms:

Location Map



Water Access

Three most commonly identified types of water points, by functionality:

per shelter:

of individuals

47%	Handpump / tube well	78%	22%	
49%	Water tank	95%	5%	Functional
5%	Tapstand	96%	4%	Non-functional

Key sectoral standards:	Target	Current Round	Achievement
# of people per functional improved water source	max. 250	26	
% of shelters with at least 1 functional improved water source³ within 200m	100%	100%	
% of functional improved water sources with no latrine within 10m	100%	61%	

Sanitation

Latrine characteristics:

Functionality and safety



Safety



Functionality



Lighting

4%	With lights
96%	Without lights

Key sectoral standards:	Target	Current Round	Achievement
# of people per functional (non-full) and safe latrine ²	max. 20	37	
# of people per functional (non-full) latrine	max. 20	34	
# of people per safe latrine ²	max. 20	33	
% of shelters with at least one functional and safe latrine ² block within 50m	100%	100%	

Targets based on long term WASH Sector Standards / Indicators for the Rohingya response, Sphere Minimum Standards as well as Department of Public Health and Environment (DPHE) Minimum Standards. Minimum standard/indicator reached, 75%-99% minimum standard/indicator reached, 50-74% minimum standard/indicator reached, indicator reached, Less than 50% of minimum standard/indicator reached.

^{1.} REACH enumerators conducted a full sweep of all sites and camps (as per boundaries defined by ISCG) and used an Open Data Kit (ODK) form to log all key infrastructure observed during this sweep, with further

REACH endinerators conducted a four sweep or all sites and camps (as per boundaries de details to be logged for WASH infrastructure.
 Safe refers to fully covered latrines (i.e. a latrine with four walls, a roof and a lockable door).
 This includes handpumps / tube wells, tapstands and water tanks.




WASH Site Profile - Camp 10

Ukhia, Cox's Bazar, Bangladesh (October 2018)
GPS Coordinates: 92.1542, 21.1897



Water Access







WASH Site Profile - Camp 10

Ukhia, Cox's Bazar, Bangladesh (October 2018)
GPS Coordinates: 92.1542, 21.1897



3

Sanitation

