




WASH Facilities - Blocked Toilets - May 2016

Layout of Single Block

- Tent
- Shower
- Kitchen
- Water Tank
- Latrine



Blocked Toilets (%) in Housing Blocks and Communal Buildings

- 0% - 5%
- 6% - 10%
- 11% - 15%
- 16% - 20%
- 21% - 40%
- 41% - 60%
- 61% - 80%
- 81% - 100%

- Fence
- ◀ Entrance


Thematic Data: 17/04/2016 - REACH
Administrative boundaries: GADM
Background imagery: Airbus 15/02/2016

Projection: WGS 1984 UTM Zone 38N


Contact : iraq@reach-initiative.org
File: IRQ_Map_IDP_Sheikhan_BlockedToilets_12June2016

Note: Data, designations and boundaries contained on this map are not warranted to error-free and do not imply acceptance by the REACH partners, associated, donors mentioned on this map.

WASH Facilities - Overflowing Toilets - May 2016



Overflowing Toilets (%) in Housing Blocks and Communal Buildings




Thematic Data: 17/04/2016 - REACH
Administrative boundaries: GADM
Background imagery: Airbus 15/02/2016

Projection: WGS 1984 UTM Zone 38N



Contact : iraq@reach-initiative.org
File: IRQ_Map_IDP_Sheikhan_OverflowingToilets_12June2016

Note: Data, designations and boundaries contained on this map are not warranted to error-free and do not imply acceptance by the REACH partners, associated, donors mentioned on this map.

WASH Facilities - Non-functioning Showers - May 2016



Non-functioning Showers (%) in Housing Blocks and Communal Buildings



Thematic Data: 17/04/2016 - REACH
Administrative boundaries: GADM
Background imagery: Airbus 15/02/2016

Projection: WGS 1984 UTM Zone 38N




Contact : iraq@reach-initiative.org
File: IRQ_Map_IDP_Sheikhan_NonFunctioningShowers_12June2016

Note: Data, designations and boundaries contained on this map are not warranted to error-free and do not imply acceptance by the REACH partners, associated, donors mentioned on this map.


WASH Facilities - Non-functioning Tap Stands - May 2016

Layout of Single Block

- Tent
- Shower
- Kitchen
- Water Tank
- Latrine



Non-functioning Tap Stands (%) in Housing Blocks and Communal Buildings



Thematic Data: 17/04/2016 - REACH
Administrative boundaries: GADM
Background imagery: Airbus 15/02/2016

Projection: WGS 1984 UTM Zone 38N

Contact : iraq@reach-initiative.org
File: IRQ_Map_IDP_Sheikhan_NonFunctioningTaps_12June2016

Note: Data, designations and boundaries contained on this map are not warranted to error-free and do not imply acceptance by the REACH partners, associated, donors mentioned on this map.