

Inter Sector Coordination BANGLADESH - Rohingya Refugee Crisis - Cox's Bazar District

Chakmarkul - Functioning and non functioning water structures For Humanitarian Purposes Only Production date: 29 May 2018





Functioning		Non Functioning		Road Network	Shelter Footprints (1.824)
•	Hand Pump - Tubewel (62)	•	Hand Pump - Tubewel (5)	———— Highway	Majhee Blocks (33)
"	Unimproved Well (0)	•	Unimproved Well (0)	Military Road / Vehicle Road	Neighboring camps
×	Unimproved Water Source (0)	×	Unimproved Water Source (0)		Camp boundary
	Chimprovou Trator Course (c)		ommprovou vrater obures (c)		Elevation Contours
•	Water Tank (12)	•	Water Tank (3)		River; Water Body
~	Tapstand (10)	*	Tapstand (1)		

Data Sources: Camp Infrastructure - REACH (22 April to 10 May) Shelter Footprints - REACH / UNOSAT (April) Roads / Footpaths - ISCG / OSM / REACH Camp / Majhee / Admin Boundaries - ISCG / IOM / OCHA

Coordinate System: WGS 1984 UTM Zone 46N Projection: Transverse Mercator Contact: reach.mapping@impact-initiatives.org

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the REACH partners, associates, donors mentioned on this map.







