


MOZAMBIQUE - Beira City - Inhamizua Posto

Neighbourhood Damage Assessment - As of 26 March 2019





39,352 buildings total*

29,498 buildings damaged**

75% of buildings damaged

*according to UNOSAT-REACH analyst building count and OSM extract from 27 March

**damage figures are the result of a rapid assessment and may be subject to change following more detailed QA/QC




Data sources:
 Damage sites - UNOSAT-REACH
 Water extent - UNOSAT
 Beira Bairros - INGC
 Administrative Boundaries (0-3) - OCHA
 Satellite Imagery Analysis: WorldView-2 from 26 March 2019
 Copyright: ©DigitalGlobe 2019
 Source: US Dept of State Humanitarian Information Unit, NextView License
 Satellite Imagery Background: WorldView-1 from 29 March 2019
 Copyright: ©DigitalGlobe 2019
 Source: US Dept of State Humanitarian Information Unit, NextView License

Legend

- Damaged Buildings
- Bairros

Damage Density

- High
- Low



Coordinate System: GCS WGS 1984
 File: MOZ_Map_CycloneIdai_InhamizuaPosto_Damage_15APR2019
 Contact: reach.mapping@impact-initiatives.org

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the REACH partners, associated, donors mentioned on this map.

