
SYRIA - Menbij


Satellite Detected Severity of Structure Damage September 2018

For humanitarian purposes only Production date: 04 February 2019





*severity calculated based on density of damaged infrastructure and weighted by scale of damage based on: destroyed, severely damaged, or moderate damage.



Damascus
RURAL
DAMASCUS
QUNEITRA
DAR'A AS-SWEIDA
JORDAN

Data sources: Admin data: Wikimapia
Satellite imagery: Pleiades from 20 September 2018

TURKEY

Menbij

Copyright: CNES Source: Airbus DS Analysis: UNITAR-UNOSAT

Production: REACH Initiative

Coordinate System: WGS 1984 UTM Zone 37N

REACH_SYR_Menbij_damagedensity_February_2019_A2 Contact: reach.mapping@impact-initiatives.org

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the REACH partners, associated, donors mentioned on this map.



L-HASAKEH