



Access to water was already problematic in the assessed locations prior to hurricane Matthew. The main sources of drinking water and water for other uses are rivers and unprotected sources or artesian wells. The main source of drinking water changed in only one location (Balagon) due to Matthew, where a well was destroyed. In some locations people have to walk several kilometers to access waterpoints.



- Main source of non-drinking water 
- Main source of drinking water 
-  Spring Water
-  Water Well
-  River
-  River (Well destroyed)
-  Departement
-  Commune
-  Section Communale

The 14 locations displayed on the map were selected as part of a REACH assessment in February 2017. For more information and the project report please visit www.reachresourcecentre.info

Data sources:
 Administrative Boundaries: CNIGS
 Localities: Openstreetmap
 Points of Interest: REACH Initiative
 Coordinate System: GCS WGS 1984
 File: HardToReach_WaterAccess_20170316
 Contact: reach.mapping@impact-initiatives.org

Note: Data, designations and boundaries contained on this map are not warranted to be error-free and do not imply acceptance by the REACH partners, associated, donors mentioned on this map.

