(i.e. part of the roof or one or more fallen walls)

Under repair: light to medium repairs have started

Destroyed: All or most of the building structure has collapsed

Areas beyond the control of Government of Ukraine as of October

Damage data - REACH, (based on Maxar WorldView

Coordinate System: WGS 1984 UTM Zone 36N

Projection: Transverse Mercator

- 3 07.04.2023)

**UADAMAGE**